

AMATEUR RADIO SERVICE - ICOM SERVICE CENTER SOUTHEAST

INVOICE

Paul Hansen, W6XA
 1140 Watkins Road
 Anderson, SC 29625
 (864) 222-3539
 pwhansen@bellsouth.net

DATE	INVOICE NO.
1/17/2007	070117001

BILL TO
Jeff Maass 9256 Concord Road Powell, OH 43065

SHIP TO
Jim Galm 3559 Townley Road Shaker Heights, OH 44122 216-295-8458

P.O. NO.	TERMS	REP	SHIP DATE	SHIP VIA	FOB	MODEL/SERIAL
Verbal	Cash	PWH	1/17/2007	Will Call	Anderson, SC	FT-1000MP/8J330156

ITEM	DESCRIPTION	UNIT	RATE	AMOUNT
Service	Located and replaced defective first mixer roofing filter. This is the stock filter on the RF board. Installed key click mod. AGC mod already installed. Installed audio mod. INRAD roofing filter already installed. During testing found maximum output at 50 watts even after changing the max power output menu item. Eventually traced to damaged flex cable connector coming from control unit. Damage probably done when AGC mod was installed. Reworked connection. Aligned and tested and adjusted key click mod. Tested TX and RX ok. This unit has the INRAD filter installed.	6	72.00	432.00
Parts	H11002202 filter set	1	73.88	73.88T
Parts	Key Click kit.	1	10.00	10.00T
Shipping	Shipping charges	1	25.83	25.83T
	Out-of-state sale, exempt from sales tax		0.00%	0.00

All work is complete!	Total	\$541.71
-----------------------	--------------	----------