

AMATEUR RADIO SERVICE

1140 Watkins Road  
 Anderson, SC 29625  
 Phone: (864) 222-3539

**INVOICE**

DATE	INVOICE NO.
5/4/2005	050504002

<b>BILL TO</b>
Jeff Maass 9256 Concord Road Powell, OH 43065

<b>SHIP TO</b>
Jeff Maass 9256 Concord Road Powell, OH 43065 614-873-3234

P.O. NO.	TERMS	REP	SHIP DATE	SHIP VIA	FOB	EQUIPMENT		
Verbal	Cash	PWH	5/4/2005	Will Call	Anderson, SC	FT-1000MP/5F010091		
ITEM	Description					Units	Rate	Amount
Service	Low power transmit on higher frequencies. Replaced defective driver transistors. Aligned TX stages.					1.5	60.00	90.00
Service	Installed adjustable key click modification and adjusted for best performance at 1KHz.					1.5	60.00	90.00
Service	Researched and installed AGC modification.					1	60.00	60.00
Service	Installed published noise blanker modification.					0.5	60.00	30.00
Service	Installed Inrad Roofing Filter modification and K9AN audio modification. Aligned RX IF gain to compensate.					0.5	60.00	30.00
Service	General condition check, alignment, performance review. Found no current problems on any of the circuit boards but there is moderate rust forming on most upper surfaces made of steel. The speaker tested generally ok here but the radio was not held while a new speaker was obtained. A new speaker is simply a plug in operation if it is replaced.					1	60.00	60.00
Parts	G3090086 2SC3133 matched pair transistors					1	31.16	31.16T
Parts	Key click modification assembly.					1	10.00	10.00T
	Out-of-state sale, exempt from sales tax						0.00%	0.00
All work is complete!						<b>Total</b>		<b>\$401.16</b>